



EMC TEST SETUP PHOTOS



EMC Report #22585 AC Line - Part 15



EMC Report #22585 Part 15, PC Peripheral



EMC Report #22585 Antenna - Substitution



EMC Report #22585 Tx Radiated