APPLICANT: MOTOROLA, INC. FCC ID: IHDT6NE1

TRANSCEIVER ADJUSTMENTS

There are no user accessible adjustments or tuning in the mobile satellite transceiver. All necessary adjustments and tuning are performed during manufacture of the product. Any adjustments or tuning after service also require special equipment and cannot be performed by the user.