



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 27, 2002

RE: FCC ID: IIO-0236W LPC

Attention: Vivi Wang

I have a few comments on this Application.

- 1 Block diagrams are required to have the frequencies and the frequency paths of all oscillators identified. Please note that the block diagram provided does not give the frequencies as required by 2.1033. Please provide a block diagram per 2.1033. **XXX**
- 2 The FCC ID label appears more than large enough to contain the 2-condition statement of 15.19. Please note that the 2-condition statement being in the manual is not justification for not putting the statement on the product. Please also note that 15.19(a)(5) is the only allowable exception. Please provide a corrected label with this 2-condition statement. Also, please explain how the label is permanently affixed to the product. **XXX**

A handwritten signature in black ink that reads "Dennis Ward".

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.