
## Test setup photographs





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-321

Phone/Fax: (913) 837-3214 Revision 1 Garmin International, Inc.

Model: A03187 Test #: 170117


Test to: CFR47 15C, RSS-210, RSS-247 File: A03187 Short Term Conf TSup

SN's: FF11 / FF12-2nd FCC ID: IPH-03187 IC: 1792A-03187

Date: February 11, 2017

Page 1 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.

Model: A03187 Test #: 170117


Test to: CFR47 15C, RSS-210, RSS-247 File: A03187 Short Term Conf TSup

SN's: FF11 / FF12-2nd FCC ID: IPH-03187 IC: 1792A-03187

Date: February 11, 2017

Page 2 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Garmin International, Inc.

Model: A03187 Test #: 170117

Test to: CFR47 15C, RSS-210, RSS-247 File: A03187 Short Term Conf TSup

SN's: FF11 / FF12-2nd FCC ID: IPH-03187 IC: 1792A-03187

Date: February 11, 2017

Page 3 of 3