



DSP Board





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Kustom Signals Inc.
Model: RP-1 Raptor
Test #:080408A
Test to: FCC Parts 2 and 15.245
File: IntPho IVQRPK

FCC ID#: IVQRPK
SN: RP01000
Page 1 of 4
Date: 4/21/2008

Display Board





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Kustom Signals Inc.
Model: RP-1 Raptor
Test #:080408A
Test to: FCC Parts 2 and 15.245
File: IntPho IVQRPK

FCC ID#: IVQRPK
SN: RP01000
Page 2 of 4
Date: 4/21/2008

Antenna Board





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Kustom Signals Inc.
Model: RP-1 Raptor
Test #:080408A
Test to: FCC Parts 2 and 15.245
File: IntPho IVQRPK

FCC ID#: IVQRPK
SN: RP01000
Page 3 of 4
Date: 4/21/2008

Planar Antenna



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Kustom Signals Inc.
Model: RP-1 Raptor
Test #:080408A
Test to: FCC Parts 2 and 15.245
File: IntPho IVQRPK

FCC ID#: IVQRPK
SN: RP01000
Page 4 of 4
Date: 4/21/2008