

Report No.: 0509349
Model No.: MH05001/0005001

hp Pursuant to FCC Part 15 Section 15.235 Emissions Requirement


MKR 19.125 msec

REF -20.0 dBm

AT 10 dB

.03 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *KW*
(Kenneth Wong)

Date: 13/5/05

Checked By: *KLW*
(Kenneth Wong)

Date: 20/5

Test Result: Pass / Fail / *NA*

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

Report No.: 0509349
Model No.: MHR05001/JJ05001

hp Pursuant to FCC Part 15 Section 15.235 Emissions Requirement


MKR 19.125 msec

REF -20.0 dBm

AT 10 dB

.05 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *K*
(Kenneth Wong)

Date: 13/5/05

Checked By: *[Signature]*
(Ivan Wong)

Date: 20/5

Test Result: Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec

Report No.: 0509348
 Model No.: MHR05001/JJ05001

HP Pursuant to FCC Part 15 Section 15.235 Emissions Requirement


MKR 1.5630 msec

REF -20.0 dBm

AT 10 dB

-.60 dB

PEAK
 LOG
 10
 dB/



WA SB
 SC LS
 CORR

Tested By: K1.
 (Kenneth Wong)

Date: 13/5/05

Checked By: [Signature]
 (Kenneth Wong)

Date: 20/5

Test Result : Pass / Fail (NA)

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec

Report No.: 0509348
 Model No: MHR05001 / JJ05001

hp Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


MKR 563.00 μ sec

REF -20.0 dBm

AT 10 dB

- .36 dB

PEAK
 LOG
 10
 dB/



Tested By: KA
 (Kenneth Wong)

Date: 13/5/05

Checked By: [Signature]
 (Iron Wong)

Date: 20/5

Test Result : Pass / Fail (NA)

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec