

EXHIBIT 6
PARTS LIST



Retlif Testing Laboratories

Test Report Number R-7999

BILL OF MATERIALS REPORT
=====

SORTED BY ASSEMBLY PART NUMBER, COMPONENT PAF
AS OF 03/26/99

CLASS CODE: 70

DSL

PART: 140-1003-00

DESC: ANTENNA PD ASSY 6217

UOM: EA SC: 119 REV:

COMPONENT PART/ REFERENCE INFO	DESCRIPTION	ITEM RV NUMBER	ST SC	QTY PER UM ASSEMBLY	YIELD FACTR
137-1003-00	PCB, ANTENNA 6217	2001	PG EA	1.000	1.000
140-1003-01	DRAWING NUMBER	00 1000	ED EA	0.000	1.000
140-1003-07	DRAWING NUMBER	06 1001	ED EA	0.000	1.000
170-1197-00	CABLE, ANTENNA	2002	MG EA	1.000	1.000
201-0032-00 01,02	TRE,RC4611,MJ423/MJ413/MJ411	2050	PG EA	2.000	1.000
203-0014-00 E1	DIODE,1N4005 500V 1A DO 41	2051	PG EA	1.000	1.000
203-0024-00 02,04	DIODE,1N4538	2052	PG EA	2.000	1.000
203-4011-00 D3	ZENER, 1N753A,0.4W,6.2V,5%	2053	PG EA	1.000	1.000
204-0006-00 MOV1	SURGE SUPP, V130LA20A,175V	2054	PG EA	1.000	1.000
236-0041-00	BUSHING,#4 NYLON	2004	PG EA	4.000	1.000
236-0042-00 01,02	INSULATOR,TO 3 SILPAD	2079	PG EA	2.000	1.000
237-0005-00	HEAT SINK TO 3 DIAMOND	2003	PG EA	2.000	1.000
261-0212-00 R6,R11	RES-MF,1/2W,1RT,5%	2055	PG EA	2.000	1.000
261-0226-00 R2,R9	RES-MF,1/2W,6R6,5%	2056	PG EA	2.000	1.000
261-0240-00 R15	RES,CF,0.68P,1/2W,22R,5%	2057	PG EA	1.000	1.000
261-0256-00 R7,R10	RES-MF-100OHM, 1/2W, 5%	2058	PG EA	2.000	1.000
261-0260-00 R5,R12,R14	RES-MF,1/2W,150R,5%	2059	PG EA	3.000	1.000
261-0272-00 R13,R17	RES,CF,470R,1/2W	2060	PG EA	2.000	1.000
261-0304-00 R16	RES-MF,10KOHM,1/2W,5%	2061	PG EA	1.000	1.000
261-0620-00 R1,R2	RES-MF,2W,10R,5%	2062	PG EA	2.000	1.000
261-0692-00 R3,R4	RES-CF,.33P,2W,10K 5%	2063	PG EA	2.000	1.000
270-0014-00 JR5-B	JUMPER,SAPE,FORMED 0.4	2064	PG EA	2.000	1.000
278-0173-00 C2	CAP,ALUM,AXIAL,160V,33U	2065	PG EA	1.000	1.000
282-0054-00 C3	CAP,CARB, 100V,33U,10%	2066	PG EA	1.000	1.000
282-1037-00 C6	CAPACITOR,ESTR 100V 100N 10%	2067	PG EA	1.000	1.000
284-0086-00 04,C8	CAP,DISC,SN,1KV,100P,10%	2068	PG EA	2.000	1.000

KPS,RE 310,E COMPONENT MANUFACTURING
 88-MAR-1999 16:29

BILL OF MATERIALS REPORT
 =====

SORTED BY ASSEMBLY PART NUMBER, COMPONENT PART
 43 OF 63/86/99

CLASS CODE: 70

B3L

PART: 1-1-1017-00

DESC: ANTENNA PD ASS: 8817

UDM: EA BD: MS REM:

COMPONENT PART REFERENCE INFO	DESCRIPTION	ITEM PK NUMBER	ST BD	QTY UM	REP ASSEMBLY	YIELD FACTR
234-0113-00 C5,C7	CAP,DISC.25F.1KDV.1N0,10%	2069	PS	EA	1.000	1.000
234-0115-00 C1	CAP,DISC.25U.10M,1KDV,5M%	2070	PS	EA	1.000	1.000
234-2065-00 C11	CAP,PLT.NPD,100V,2PF	2071	PS	EA	1.000	1.000
234-2066-00 C13	CAPACITOR,PLATE NPD 100V 4PF	2072	PS	EA	1.000	1.000
234-2077-00 C12	CAPACITOR,PLATE NPD 100V 22PF	2073	PS	EA	1.000	1.000
238-0017-00 C9	CAP,MID4.1KV.5100PF.1%	2074	PS	EA	1.000	1.000
238-0014-00 T1	CTR,T1. DIGITR40	2075	MS	EA	1.000	1.000
238-0018-00 L1,LE	INDUCTOR, 5M%	2076	MS	EA	1.000	1.000
350-1941-00 J81,J82,J83,J84	WIRE #33 SOLID, 3ARE	2077	PS	FT	0.200	1.000
370-0005-00	CABLE,TIE 4" LOCKING	2014	PS	EA	1.000	1.000
372-0007-00	TLV INEUL. #30 WHT TEFLON	2011	PS	FT	0.120	1.000
372-0011-00	ELV INEUL #20 TEFLON	2012	PS	FT	0.120	1.000
376-0817-00	STUD,PEK, 4-40 X 0.50	2005	PS	EA	4.000	1.000
376-1014-00	SCREW,PHIL,PAR,4-40,0.750	2010	PS	EA	1.000	1.000
376-1115-00	SCREW,PHIL,10-32,1.000	2011	PS	EA	2.000	1.000
386-0217-00	NUT,HEX, 4-40, .250 A/F	2007	PS	EA	5.000	1.000
386-0217-00	NUT,HEX, 10-32, 0.375 A/F	2015	PS	EA	2.000	1.000
390-0017-00	FIBRE WASHER,#4,0.250 ID	2013	PS	EA	1.000	1.000
390-0017-00	FIBRE WSHR, #10, 0.375 ID	2010	PS	EA	2.000	1.000
391-0215-00	WASHER,SPLIT LOCK #4	2006	PS	EA	5.000	1.000
391-0215-00	WASHER,SPLIT LOCK #10	2017	PS	EA	2.000	1.000
426-0044-00	SILICONE, RTV 707, CLEAR	2008	PS	EA	0.100	1.000
J075961	LABEL	2999	ES	EA	1.000	1.000