

Mike Kuo

Subject: FW: Re : Logitech Far East Ltd., FCC ID: JNZ212175 , Assessment NO.: AN06T5702, Notice#1--Updated (0425)

Attachments: Y-RAP78_User's manual(0425).pdf; Y-RAP78_Report(RP1-1)0425.pdf; Y-RAP78_Internal Photo(0425).pdf; Y-RAP78_External Photo(0425).pdf; Y-RAP78_Setup Photo(0425).pdf

<mike.kuo@ccsemc.com>

收件人： <mike.kuo@ccsemc.com>

2006/04/24 01:32 PM

副本抄送： <lucy.tsai@tw.ccsemc.com>

主旨： Logitech Far East Ltd., FCC ID: JNZ212175 , Assessment NO.: AN06T5702, Notice#1

Hi Mike,

This is 27MHz wireless keyboard, submitted by HsinChun lab and was requested to get grant tomorrow. The question I got are as below.

1. The EUT drawing indicated in User manual is different from external photos. Please make sure if the manual submitted is correct.

Ans:Please find the attached for update user's manual(0425).

2. According to the schematic, a RFID antenna and U5 of RFID EM4134,NM are used which doesn't agree this application. Please clarify if it's a RFID and provide its specification.

Ans:Please see our client's reply:

This product is a passive RFID device(similar to Tag). For RFID, we use frequency 13.56MHz ,and for RF communication with Receiver (connecting computer), we have two channels which is $13.5475\text{MHz} \times 2 = 27.045\text{MHz}$ and $13.5725\text{MHz} \times 2 =$

27.145MHz. So that's why we have two X'tals for oscillator circuit.

3. Test report shown EUT has been investigated with x, y, z axis, and Y axis was the worst case and reported.

Please explain why a keyboard was required to be measured in X, Y, Z axis.

Ans:Please find the attached for update test report & setup photo(0425).

4. Please provide the another internal photo to show the rear side of the main PCB board.

Ans:Please find the attached for update Internal & External photo(0425).

Best Regards,

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains

4/25/2006

confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.