



Annex F

Spurious Emissions FCC Part 25.216(f)


25.216f_1605 - 1610 MHz_1 MHz RBW_C8400_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_C8400_1636.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_C8400_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X16_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X16_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X16_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X32_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X32_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X32_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X64_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X64_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T2.5X64_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X16_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X16_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X16_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X32_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X32_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X32_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X64_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X64_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_FR80T5X64_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T0.5QD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T0.5QD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T0.5QD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T1QD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T1QD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R20T1QD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T1XD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T1XD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T1XD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2QD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2QD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2QD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2XD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2XD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T2XD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5QD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5QD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5QD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5XD_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5XD_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_R5T4.5XD_1660.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_RT10500_1626.5 MHz_(worst case)




25.216f_1605 - 1610 MHz_1 MHz RBW_RT10500_1636.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_RT10500_1646.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_RT1200_1626.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_RT1200_1636.5 MHz_




25.216f_1605 - 1610 MHz_1 MHz RBW_RT1200_1646.5 MHz_



25.216f_1605 - 1610 MHz_1 MHz RBW_RT600_1626.5 MHz_



25.216f_1605 - 1610 MHz_1 MHz RBW_RT600_1636.5 MHz_



25.216f_1605 - 1610 MHz_1 MHz RBW_RT600_1646.5 MHz_

