


Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification




© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0

Test Report S/N: 95.2000207075.KNZ  
Test Date(s): February 16-18, 2000

FCC Part 95  
Certification



© 2000 PCTEST Lab

FCC ID: KNZ48413 (Tx/Rx 462.6375 MHz)  
DSI (HK) Ltd 2-Way Portable FM Wrist-worn Radio Transceiver (FRS)

NMLAP Lab Code: 100431-0