




Passive Start Only



Passive Entry
Passive Start
(Fully populated)



FCC Call out to be insert molded. Letters to be raised 0.25mm.