




Passive Start Only



Passive Entry  
Passive Start  
(Fully populated)



FCC Call out to be insert molded. Letters to be raised 0.25mm.