

INTERTEK TESTING SERVICES

Pursuant to FCC Part 15 Section 15.222 Emissions Requirement

Report No.: 031187
Model No.: 600790

4463 *[Signature]*

DLT: 23.4ms


0.04dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: *[Signature]*

Date: 10-7-03

Checked By: *[Signature]*

Date: 12/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 100ms

F: 27.145400MHz

INTERTEK TESTING SERVICES

Report No.: 0311187
 Model No.: 6002790
 4463

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


DLT: 560us

-0.08dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: *(Signature)*

Date: 10-7-03

Checked By: *(Signature)*

Date: 15/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 35ms

F: 27.145400MHz

INTERTEK TESTING SERVICES

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

Report No.: 0311187
 Model No.: 6002790
 4463

PLT: 1.69ms


-0.13dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: *[Signature]*

Date: 10-7-03

Checked By: *[Signature]*

Date: 15/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 35ms

F: 27.145400MHz

INTERTEK TESTING SERVICES

Report No.: 031118+
 Model No.: 6002790
 4463

Pursuant to FCC Part 15 Section 15. 222 Emissions Requirement

DLT: 23.45ms


0.04dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By:

Date: 10-7-03

Checked By:

Date: 15/7/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 35ms

F: 27.145400MHz