

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL21CW	Page 1(5)
Author Data Daoud Attayi	Dates of Test Sep 08-29, 2009	Report No RTS-2068-0909-35

Annex E: Test Setup Photos

Author Data Daoud Attayi	Dates of Test Sep 08-29, 2009	Report No RTS-2068-0909-35	FCC ID L6ARCL20CW
------------------------------------	---	--------------------------------------	-----------------------------




Figure 1 - BlackBerry® Smartphone

Author Data Daoud Attayi	Dates of Test Sep 08-29, 2009	Report No RTS-2068-0909-35	FCC ID L6ARCL20CW
------------------------------------	---	--------------------------------------	-----------------------------




Figure E2: Probe calibration and reference signal measurement setup

RIM Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL21CW	Page 4(5)
Author Data Daoud Attayi	Dates of Test Sep 08-29, 2009	Report No RTS-2068-0909-35




Figure E3: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL21CW	Page 5(5)
Author Data Daoud Attayi	Dates of Test Sep 08-29, 2009	Report No RTS-2068-0909-35




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup