

	Document Annex E_Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCU21CW		Page 1(5)
Author Data Daoud Attayi	Dates of Test May 17-18, June 02-03, 2010	Report No RTS-2581-1006-03	FCC ID L6ARCU20CW

Annex E: Test Setup Photos

	Document Annex E_Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCU21CW		Page 2(5)
Author Data Daoud Attayi	Dates of Test May 17-18, June 02-03, 2010	Report No RTS-2581-1006-03	FCC ID L6ARCU20CW



Figure 1. BlackBerry Smartphone

	Document Annex E_Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCU21CW		Page 3(5)
Author Data Daoud Attayi	Dates of Test May 17-18, June 02-03, 2010	Report No RTS-2581-1006-03	FCC ID L6ARCU20CW




Figure E2: Probe calibration and reference signal measurement setup

	Document Annex E_Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCU21CW		Page 4(5)
Author Data Daoud Attayi	Dates of Test May 17-18, June 02-03, 2010	Report No RTS-2581-1006-03	FCC ID L6ARCU20CW





Figure E3: Ambient noise and system validation measurement setup

	Document Annex E_Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCU21CW		Page 5(5)
Author Data Daoud Attayi	Dates of Test May 17-18, June 02-03, 2010	Report No RTS-2581-1006-03	FCC ID L6ARCU20CW




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup