

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RCX71UW			Page 1(5)
Author Data Daoud Attayi	Dates of Test Feb. 26-Mar. 04, 2010	Report No RTS-2474-1003-02	FCC ID L6ARCX70UW	

Annex C: Test set up photos

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RCX71UW		Page 2(5)
Author Data Daoud Attayi	Dates of Test Feb. 26-Mar. 04, 2010	Report No RTS-2474-1003-02	FCC ID L6ARCX70UW



Figure 1. BlackBerry Smartphone

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RCX71UW			Page 3(5)
Author Data Daoud Attayi	Dates of Test Feb. 26-Mar. 04, 2010	Report No RTS-2474-1003-02	FCC ID L6ARCX70UW	




Figure 2 – Dipole Validation & Probe Modulation Factor measurement setup

Author Data

Daoud Attayi

Dates of Test

Feb. 26-Mar. 04, 2010

Report No

RTS-2474-1003-02

FCC ID



L6ARCX70UW

Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RCX71UW		Page 5(5)
Author Data Daoud Attayi	Dates of Test Feb. 26-Mar. 04, 2010	Report No RTS-2474-1003-02	FCC ID L6ARCX70UW





Figure 4 – HAC RF emissions test setup