

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDU71CW/RDE71UW			Page 1(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 28, 2011	Report No RTS-3933-1104-55A RTS-2580-1106-36	FCC ID L6ARDU70CW L6ARDE70UW	

Annex C: Test set up photos

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDU71CW/RDE71UW			Page 2(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 28, 2011	Report No RTS-3933-1104-55A RTS-2580-1106-36	FCC ID L6ARDU70CW L6ARDE70UW	

Audio Output (0, 0)

Telecoil (-3mm, 10mm)



Figure C1. BlackBerry Smartphone

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDU71CW/RDE71UW			Page 3(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 28 , 2011	Report No RTS-3933-1104-55A RTS-2580-1106-36	FCC ID L6ARDU70CW L6ARDE70UW	





Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDU71CW/RDE71UW			Page 4(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 28, 2011	Report No RTS-3933-1104-55A RTS-2580-1106-36	FCC ID L6ARDU70CW L6ARDE70UW	





Figure C3 – HAC RF emissions test setup