

 <p>Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDE71UW</p>			Page 1(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51A RTS-2580-1106-37	FCC ID L6ARDU70CW L6ARDE70UW

Annex E: Test set up photos

	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDE71UW	Page
	Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51A RTS-2580-1106-37
			FCC ID L6ARDU70CW L6ARDE70UW



Figure E1. BlackBerry Smartphone

	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDE71UW	Page
			3(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51A RTS-2580-1106-37	FCC ID L6ARDU70CW L6ARDE70UW





Figure E2: Ambient noise and system validation measurement setup

	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDE71UW	Page
			4(4)
Author Data Daoud Attayi	Dates of Test Mar. 09-28, 2011	Report No RTS-3933-1105-51A RTS-2580-1106-37	FCC ID L6ARDU70CW L6ARDE70UW




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup