

| | | |
|----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
|  | Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW | Page 1(5) |
| Author Data Daoud Attayi | Dates of Test Jan. 12-13, 2011 | Report No RTS-3640-1102-01 |

Annex C: Test set up photos

| | | | |
|----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------------------------|
|  | Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW | Page 2(5) | |
| Author Data Daoud Attayi | Dates of Test Jan. 12-13, 2011 | Report No RTS-3640-1102-01 | FCC ID L6ARDM70UW |



Figure 1. BlackBerry Smartphone

| | | |
|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| RIM Testing Services™ | Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW | Page 3(5) |
| Author Data Daoud Attayi | Dates of Test Jan. 12-13, 2011 | Report No RTS-3640-1102-01 FCC ID L6ARDM70UW |




Figure 2 – Dipole Validation & Probe Modulation Factor measurement setup

| | | |
|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| RIM Testing Services™ | Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW | Page 4(5) |
| Author Data Daoud Attayi | Dates of Test Jan. 12-13, 2011 | Report No RTS-3640-1102-01 FCC ID L6ARDM70UW |




Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

| | | |
|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| RIM Testing Services™ | Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDM71UW | Page 5(5) |
| Author Data Daoud Attayi | Dates of Test Jan. 12-13, 2011 | Report No RTS-3640-1102-01 |




Figure 4 – HAC RF emissions test setup