

 <p>Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDH71CW/RDQ71UW</p>			Page 1(4)
Author Data Daoud Attayi	Dates of Test Mar. 18-21, 2011 April 04, 2011	Report No RTS-2605-1104-43B	FCC ID L6ARDH70CW L6ARDQ70UW

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDH71CW/RDQ71UW	Page 2(4)
Author Data Daoud Attayi	Dates of Test Mar. 18-21, 2011 April 04, 2011	Report No RTS-2605-1104-43B FCC ID L6ARDH70CW L6ARDQ70UW




Figure E1. BlackBerry Smartphone

	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDH71CW/RDQ71UW	Page
			3(4)
Author Data Daoud Attayi	Dates of Test Mar. 18-21, 2011 April 04, 2011	Report No RTS-2605-1104-43B	FCC ID L6ARDH70CW L6ARDQ70UW





Figure E2: Ambient noise and system validation measurement setup

RIM Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDH71CW/RDQ71UW	Page 4(4)
Author Data Daoud Attayi	Dates of Test Mar. 18-21, 2011 April 04, 2011	Report No RTS-2605-1104-43B




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup