

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 1(5)
Author Data Daoud Attayi	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18B

Annex C: Test set up photos

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 2(5)
Author Data Daoud Attayi	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18B FCC ID L6ARDD70UW L6ARDX70UW



Audio Output (0, 0)

Telecoil (-5mm, 13mm)




Figure C1. BlackBerry Smartphone

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 3(5)
Author Data Daoud Attayi	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18B FCC ID L6ARDD70UW L6ARDX70UW



RIM Testing Services™	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 4(5)
Author Data Daoud Attayi	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18B

Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup



	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 5(5)
Author Data Daoud Attayi	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18B

Figure C3 – HAC RF emissions test setup