

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/REM71UW			Page 1(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 05 , May 13-16, 2011	Report No RTS-2579-1107-18C	FCC ID L6ARDD70UW L6AREM70UW	

Annex C: Test set up photos

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/REM71UW			Page 2(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 05, May 13-16, 2011	Report No RTS-2579-1107-18C	FCC ID L6ARDD70UW L6AREM70UW	

Audio Output (0, 0)

Telecoil (-5mm, 13mm)



Figure C1. BlackBerry Smartphone

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/REM71UW		Page 3(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 05, May 13-16, 2011	Report No RTS-2579-1107-18C	FCC ID L6ARDD70UW L6AREM70UW





Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/REM71UW		Page 4(4)
Author Data Daoud Attayi	Dates of Test Mar. 22-23, Apr. 05, May 13-16, 2011	Report No RTS-2579-1107-18C	FCC ID L6ARDD70UW L6AREM70UW





Figure C3 – HAC RF emissions test setup