

|                                                                                   |                                                                                                                                     |                                      |                              |
|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------------------|
|  | Document<br><b>Annex C to Hearing Aid Compatibility RF Emissions Test<br/> Report for the BlackBerry® Smartphone model RFQ121LW</b> |                                      | Page<br><br><b>1(4)</b>      |
| Author Data<br><b>Daoud Attayi</b>                                                | Dates of Test<br><b>Feb. 17-29, June 28, 2012<br/> April 24-26, 2013</b>                                                            | Report No<br><b>RTS-6026-1304-52</b> | FCC ID<br><b>L6ARFQ110LW</b> |

## Annex C: Test set up photos



|                                                                                   |                                                                                                                                |                                      |                              |
|-----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------------------|
|  | Document<br><b>Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RFQ121LW</b> |                                      | Page<br><b>2(4)</b>          |
| Author Data<br><b>Daoud Attayi</b>                                                | Dates of Test<br><b>Feb. 17-29, June 28, 2012</b><br><b>April 24-26, 2013</b>                                                  | Report No<br><b>RTS-6026-1304-52</b> | FCC ID<br><b>L6ARFQ110LW</b> |

Audio Output (0, 0)




**Figure C1. BlackBerry Smartphone**

|                                                                                   |                                                                                                                                     |                                      |                              |
|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------------------|
|  | Document<br><b>Annex C to Hearing Aid Compatibility RF Emissions Test<br/> Report for the BlackBerry® Smartphone model RFQ121LW</b> |                                      | Page<br><b>3(4)</b>          |
| Author Data<br><b>Daoud Attayi</b>                                                | Dates of Test<br><b>Feb. 17-29, June 28, 2012<br/> April 24-26, 2013</b>                                                            | Report No<br><b>RTS-6026-1304-52</b> | FCC ID<br><b>L6ARFQ110LW</b> |



**Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup**

|                                                                                   |                                                                                                                                |                                      |                              |
|-----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------------------|
|  | Document<br><b>Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RFQ121LW</b> |                                      | Page<br><b>4(4)</b>          |
| Author Data<br><b>Daoud Attayi</b>                                                | Dates of Test<br><b>Feb. 17-29, June 28, 2012<br/>April 24-26, 2013</b>                                                        | Report No<br><b>RTS-6026-1304-52</b> | FCC ID<br><b>L6ARFQ110LW</b> |



**Figure C3 – HAC RF emissions test setup**