

BlackBerry RTS	Document			Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW			1(4)
Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29	FCC ID L6ARGF110LW	

Annex E: Test set up photos

BlackBerry RTS	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW		Page 2(4)
	Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29
		FCC ID L6ARGF110LW	




Figure E1. BlackBerry Smartphone

BlackBerry RTS	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW		3(4)
Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29	FCC ID L6ARGF110LW





Figure E2: Ambient noise and system validation measurement setup

BlackBerry RTS	Document			Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW			4(4)
Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29	FCC ID L6ARGF110LW	




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup