

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHK211LW (STV100-1)		Page 1(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-23, 2015	Report No RTS-6066-1509-20	FCC ID L6ARHK210LW

Annex E: Test set up photos

	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHK211LW (STV100-1)		2(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-23, 2015	Report No RTS-6066-1509-20	FCC ID L6ARHK210LW



Figure E1. BlackBerry Smartphone, Slider Closed

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHK211LW (STV100-1)		Page 3(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-23, 2015	Report No RTS-6066-1509-20	FCC ID L6ARHK210LW



Figure E2. BlackBerry Smartphone, Slider Open

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHK211LW (STV100-1)		Page 4(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-23, 2015	Report No RTS-6066-1509-20	FCC ID L6ARHK210LW





Figure E3: Ambient noise and system validation measurement setup

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHK211LW (STV100-1)		Page 5(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-23, 2015	Report No RTS-6066-1509-20	FCC ID L6ARHK210LW





Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup