



# Intertek Testing Services

## ETL SEMKO

Report No.: 00024081 *Transmit Mode*

Tested By: Hong, Report No.: 00024081


Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |       |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |





# Intertek Testing Services

## ETL SEMKO

Report No.: 00024081 *Transmit Mode*

Tested By: Hong, Report No.: 00024081

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge

450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.45000 25.5 48.0

0.75000 28.8 48.0

0.78000 28.9 48.0

29.48500 35.7 48.0

\* limit exceeded