



Cisco Systems, Inc.
125 West Tasman Drive
San Jose, CA 95134-1706
USA
Phone: 408-526-4000
Fax: 408-526-4100
<http://www.cisco.com>

Identity Declaration Letter and deviation statement

Date: December 1, 2021

Identity Declaration statement

Cisco Webex Room Bar (model TTC7-28) used Cisco module with Part number 07-100577 (FCC ID: LDK073002357, IC: 2461N-073002357).

This module has been previously changed ID from Murata (FCC ID: VPYLBEE5XV1XA, IC: 772C-LBEE5XV1XA) to Cisco's. The Murata module now under Cisco's FCC/IC IDs remains unchanged electromagnetically and mechanically.

Deviation Statements

The software deviations is:

- Output power is reduced on channels as listed below.

Frequency	Modulation	Channel	Original power	Reduced power
5GHz	11n20 11a	40	13.5	10
5GHz	11n20	56	15	14.5
5GHz	11n20	60	15	10.5
5GHz	11n20	64	10	9.5
5GHz	11n20 11a	104	15	12
5GHz	11n20 11a	136	15	13
5GHz	11a	60	15	12
5GHz	11a	64	10.5	10
5GHz	11n 20 MIMO	40	10.5	10
5GHz	11n 20 MIMO	60	14	10.5
5GHz	11n 20 MIMO	104	14.5	10
5GHz	11n 20 MIMO	136	14.5	13
5GHz	11n 40 MIMO	54	14	13
5GHz	11n 40 MIMO	110	14	13.5

EUT uses different external antennas than the ones in Murata certificates.

Please refer to the antenna datasheet for details.

The Cisco module 07-100577 is placed into a host configuration.

Signature

Name and Job Title.

: Samuel Kim, Leader, Business Operations

E-mail

: Samukim@cisco.com

Tel.

: +1 (408) 526-4000