



Intertek Testing Services

ETL SEMKO

Report No.: 9913333

Tested By: Hong, Report No.: 9913333


Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|----------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN | OFF 60dB |

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name |
|----------------|-------|------|-------|
| 3 | 9k | 30M | EI078 |



PAGE 1

MHz

Ctrl No.: NA



Report No.: 9913333

Tested By: Hong, Report No.: 9913333

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results