Mike Kuo

From: eric@ccsemc.com.tw

Sent: December04日2003年Thursday 5:17 AM

To: Steve Cheng Cc: Mike Kuo

Subject: 回信: AN03T3375 UC-Logic M35UCWPK01



Aflobu

(MOS-10) TestRpt (Rev.01).pdf

ot (MOS-10) JserMan_Revised.pd

Hi, Steve,

Please review our replies upon your comment, as follows:

Q1 & 4: Please find the attached user manual which is modified upon your comment.

Q2: All the testes are carried with the Loop Antenna (EMCO 6502), details can be found on the pages 12.

Q3: Please find the attached report which is revised upon your comment.

Thank you!!

Should you have any question, please don't hesitate to ask me.

Best regards,

Eric Wong

Compliance Certification Services Inc. (Formerly C&C Laboratory Co., Ltd.)

Tel.: +886-3-3240332 Ext.49

Add.: No.81-1, Lane 210, Ba-de 2nd Rd., Luchu Hsiang, Taoyuan Hsien 338,

Taiwan, R.O.C.

Email: eric@ccsemc.com.tw URL: http://www.ccsemc.com.tw

(See attached file: (MOS-10) TestRpt (Rev.01).pdf)(See attached file:

(MOS-10) UserMan_Revised.pdf)

Steve Cheng

<SCheng@CCSEMC.co 收件人: "Eric (E-mail)" <eric@ccsemc.com.tw>

m> 副本抄送: Mike Kuo <MKUO@CCSEMC.com>

主旨: AN03T3375 UC-Logic M35UCWPK01

2003/12/02 12:09

PM

RT for project: AN03T3375 UC-Logic M35UCWPK01

Subject:

Question #1: 15.21 warning label could not be found in users manual or on

the device.

Question #2: Test report P14, please declare which antenna was used for

300K

fundamental emission measurement.

Question #3: Test report P14, Please explain how 118.66 dBuv limit is obtained.

Question #4: Per Section 15.19 Labeling requirements. Following label is required. However it cannot be found on EUT label or users manual. Please clarify.

This device complies with Part 15 of the FCC Rules. Operation is subject to

the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Best Regards

Steve Cheng / TCB Technical Reviewer Compliance Certification Services 561F Monterey Road Morgan Hill, CA 95037 Tel:(408) 463-0885 x: 119 Fax:(408) 463-0888 scheng@ccsemc.com http:\\www.ccsemc.com