聯民科技企業有限公司 SUPER NOVA CO. LTD.

台灣省台北縣五股鄉 248 五股工業區五權六路 34號 NO. 34 WU-CHUAN 6 RD. WU-KU TAIPEI HESIEN, TAIWAN, R.O.C INDUSTRIAL ZONE WU-KU HSIANG


電話:(02)22982221(代表號)

TEL:886-2-22982221(8 Lines)

傳真:(02)22981083,22989499 FAX:886-2-22981083, 22989499

E-mail: fairnova@ms64. hinet. net

Notice: The changes or modifications not expressly approved by the pacty responsible for compliance could void the user's authority to operate the equipment.



Important:

- 1. It is recommended to mount the sensor in the center of the car under the rear seat.
- 2. Avoid to mount the sensor directly behind the metal obstacles.
- 3. Connect the power after installation, must delay 5 seconds to testing and adjusting the sensor.
- 4. Remember to isolate with diods, if this sensor's output is parallel connected to any other sensors.

FCC ID: M65NVMWS ϕ 2 THIS DEVICE COMPLIES WITH PART 15 OF THE FCCRULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS:(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESRIED OPERATION.

The user should not modify or change this equipment without written approval form (SUPER NOVA CO., LTD) Modification void authority to use this equt.