

Federal Communications Commission
7345 Oakland Mills Road
Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: MBPUTRUST47X0F-01

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by Identiv, Inc will establish a new FCC ID under Identiv, Inc grantee code for the purpose of marketing.

The original grant to MBP with FCC ID: CLOUD47X0F-001 will remain in effect.

An authorization letter by Identiv, Inc is attached.


Per 2.933(b)

- 1.) The original identification is: FCC ID:MBPCLOUD47X0F-001
- 2.) The original granted date is: 12/20/2012
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Label and Location Info

Sincerely



Name: Calai Bhoopathi
Title: Senior Engineer
Date: 02/10/2015