



Enfora, Inc.
661 E. 18th Street
Plano, TX 75074-5601
(972) 633-4400
Fax (972) 633-4444

January 26, 2007

Tune-Up Procedure Description for GSM0308

Power Adjustments

The RF power output of the modem is preset during the manufacturing process via software-controlled adjustment of calibration parameters referenced to a base-station simulator.

Under normal operation, the RF output power is maintained via an ALC circuit. Neither the integrator nor end-user has access to the calibration/power adjustment of the device.

Frequency Adjustments

Under normal operation, the transmitter uses a frequency synthesizer synchronized to a base-station clock, thus there are no frequency alignments that must be made.

Scott Yarberry

A handwritten signature in black ink that reads "Scott Yarberry".

AVP, Product Development
Enfora, L.P.
661 E. 18th St
Plano, TX 75074
972-633-4400