

Correspondence by Project

Project Number:

-192134580

Correspondence Number	Memo
MKYMRXF102RX-1	>>> 1) Please submit a block diagram as per FCC Part 2, Section 2.1033(b)(5). The Block Diagram has been uploaded into the Exhibits >>>2) The sample FCC Label submitted is not sufficient. It must read "FCC ID: MKYMRXF102RX", and not "FCC: MKYMRXF102RX". A Revised FCC Label has been submitted under Exhibits >>>3) According to section 4.1 of the test report, the device under test was connected to a main module and several cables were attached to its terminal blocks. On the test setup photos; however, it appears that the unit was tested as a stand alone unit. Also, under section 4.1.1, it is stated that there were no cables. Please explain. The test setup pictures in the report were not correctly changed to reflect the correct test setup. A revised test report has been uploaded to exhibits that will include the correct test setup photos.