

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

March 16, 2005

RE: FCC ID: MOIPULS616263_ATCB002219

Attention: Kathy Grzovic

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please provide a completed RSP100 form. Please provide the emissions designator information for this device. Please note that these devices generally have PON as the designator. The emissions designator then would be your measured bandwidth information then the PON. For example 800MP0N.

Response: Please excuse the oversight. A revised RSP100 form was uploaded with this response.

2. Please note that neither the report nor other documentation shows that the antenna connection for the new antenna meets 15.203 requirements. Please provide evidence or attestation that the new antenna meets this requirement.

Response: The antenna connection is not a standard antenna jack, but instead was designed by the manufacturer. A customer could install a replacement antenna, but only one obtained from the manufacturer. No other antennas can be used with this connector, as no other antenna would fit.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination.

Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.