



Version	Description	Date	Signature
V01	Final version release	2021/12/27	Chen, C.R.
V02	Update Part number and EAC QR Code	2022/02/27	Chen, C.R.
			Shen, C.S.
			Lin, H.W.
			Lin, H.W.

A Cover LABEL LOCATION




No need label

B Cover LABEL LOCATION



C Cover LABEL LOCATION




Intel label H01F000400 15100-02700000	GeForce label H01F000400 15100-02700000	GPU iRS label H01F000400 15100-02700000	ENERGY Label H01F000400 H01F000400	HDMI label H01F000400 15100-01750100	TUV Label H01F000400 15100-22330000

區域 1 Label

INSURANCE KASKO LABEL H01F000400 15100-02700000	VIETNAM SERVICE STICKER H01F000400 15100-02700000	BRAZIL WARRANTY Label H01F000400 15100-02700000	JP CALL CENTER Label H01F000400 15100-02700000	2YR WARRANTY label H01F000400 15100-02700000
意大利	越南	巴西	日本	南非
ACTH-PREPERCT WARRANTY-LB H01F000400 15100-14384000	SERVICE Label H01F000400 15100-21571000	TOD Label H01F000400 15100-22810100	WEBSITE QR CODE LABEL BY 標識	
泰國	印尼	歐洲	美國	

D Cover LABEL LOCATION



區域 1 Label

MANUFACTURE NAME H01F000400 15100-02700000	RUS MADE IN CHINA H01F000400 15100-02700000	MEXICO SUPPORT H01F000400 15100-02700000	KCC PRODUCT H01F000400 15100-02700000	MOROCCO H01F000400 15100-14900000	ENERGY EFF H01F000400 15100-02700000	ACU PC RECYCLE H01F000400 15100-02700000
TAIWAN PRODUCTION WARNING H01F000400 15100-04735400	INDON. IMPORTER H01F000400 15100-02700000	CZ/SK TECHNICAL SUPPORT H01F000400 15100-03967000	EPAD FRN EN50332 H01F000400 15100-00950000	MY SIRIM H01F000400 15100-12630000	EEB TECHNICAL SUPPORT H01F000400 15100-03967000	ACI TECHNICAL SUPPORT H01F000400 15100-03967000

區域 2 Label

EPAD FRN EN50332 WORDING H01F000400 15100-00950000	TAIWAN NCC WARNING H01F000400 15100-04735400	STYLUS NCC H01F000400 15100-22814000