


Prüfbericht - Nr.: 16020577 001
Test Report No.:

Seite 16 von 18
Page 16 of 18

6 Photographs of the Test Set-Up

Note: “HP4892” showed on the test setup photo is the internal name code of the receiver.

Photograph 1: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.: 16020577 001
Test Report No.:

Seite 17 von 18
Page 17 of 18

Photograph 2: Set-up for Radiation Measurement above 1GHz

