



Intertek Testing Services

ETL SEMKO

Report No.: 0210331
Receiving
(Left)

Tested By: Hong, Report No.: 0210331


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0210331
Receiving
(Left)

Tested By: Hong, Report No.: 0210331

Scan Settings (1 Range)

----- Frequencies -----			Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.45000	25.7	48.0
0.73000	22.2	48.0
0.77500	21.0	48.0

* limit exceeded



Intertek Testing Services

ETL SEMKO

Report No.: 0210331
Receiving
(Right)

Tested By: Hong, Report No.: 0210331

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0210331
Receiving
(Right)

Tested By: Hong, Report No.: 0210331

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.45000	26.0	48.0
0.69000	20.8	48.0

* limit exceeded

Ctrl No.: N/A