


APPENDIX 1: Photographs of test setup

Conducted Emission

Front



Rear



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124


MF060b(14.06.06)

Spurious Emission (Radiated)

Front



Rear



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124


MF060b(14.06.06)

Worst Case Position (X-axis:Horizontal / Y-axis:Vertical)

X-axis



Y-axis



Z-axis

