

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

Worst Case Position

Module

Frequency Range	Horizontal	Vertical
Below 1 GHz	X-axis	X-axis
Above 1 GHz	Y-axis	Y-axis
Spurious (6 GHz)	Y-axis	X-axis
Spurious (13 GHz)	Z-axis	Y-axis

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Antenna

Frequency Range	Horizontal	Vertical
Below 1 GHz	X-axis	X-axis
Above 1 GHz	X-axis	Z-axis
Spurious (6 GHz)	Y-axis	Z-axis
Spurious (13 GHz)	Z-axis	Z-axis


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report