


8. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION



X-AXIS BACK PHOTO





Y-AXIS BACK PHOTO



Y-AXIS WITH CRADLE FRONT PHOTO



Y-AXIS BACK WITH CRADLE PHOTO



END OF REPORT