


5.5. Photographs of Couducted Powerline Test Configuration

- The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : N9Q99NS23PS

Page No. : 14 of 22

Issued Date : Aug. 11, 1999



SIDE VIEW

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : N9Q99NS23PS

Page No. : 15 of 22


Issued Date : Aug. 11, 1999

6.5. Photographs of Radiated Emission Test Configuration

- The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : N9Q99NS23PS

Page No. : 20 of 22

Issued Date : Aug. 11, 1999