



Intertek Testing Services

ETL SEMKO

Report No.: 0102817

Tested By: Ben, Report No.: 0102817

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0102817

Tested By: Ben, Report No.: 0102817

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.45000	38.7	48.0
0.59500	37.1	48.0
0.98500	33.2	48.0
1.07000	33.5	48.0
1.29000	28.6	48.0
1.77500	18.1	48.0
2.47500	29.9	48.0
28.63500	33.8	48.0

* limit

Ctrl No.: N/A