




Photo 2: Exploded View, Pad-1000




Photo 3: Interior View, Battery Removed, PAD-1000

This is a general view; detail photos are available within.




Photo 1: RF Board, Top View, PAD-1000, Modified





Photo 2: RF Board, Bottom View, PAD-1000, Modified

NBI-PAD1000 RF shield can removed



LambdaMetrics, Inc.
P.O. Box 1029
Cedar Park, TX. 78630-1029




Photo 1: RF Board, Top View, PAD-1000, Modified

COPY
11-11-98




Photo 2: RF Board, Bottom View, PAD-1000, Modified





Photo 4: Detail View, Board Stack, PAD-1000

Note antenna (on right) is not removable.



(512) 219-8218




Photo 6: RF Board, Outside of Enclosure, PAD-1000




Photo 7: RF Board, Bottom View, PAD-1000




Photo 8: Digital Board, Top View, PAD-1000




Photo 9: Digital Board, Bottom View, PAD-1000