



January 20, 2011

To Whom It May Concern;

In the case of the XT models 06418, the GSM modem module output power for GSM850 is limited to +33dBm and +30dBm for PCS1900. Our antenna is fairly inefficient and has some losses. The measured Total Radiated Power (TRP) is within the expected range.



J. Chris Defant