



Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypad	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				



COMP. PRINT


Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypad	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				



COMP. MASK


Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypad	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				

SIZE	QTY	SYM	PLTD
0.4	241	+	PLTD
1	46	□	PLTD
1.1	14	◇	PLTD
0.3	8	V	PLTD
0.25	30	W	PLTD
0.5	74	X	PLTD
0.6	2	Y	PLTD
0.9	2	Z	PLTD




DRILL DWG

Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypad	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				




COMP. LAYER

DrillDrawing	34	0n
CarbonKerpad	18	01t
SolderPrint	29	0n
CompPrint	36	0n
Insulation	30	01t
CarbonPlate	51	01t
SolderMask	28	0n
SolderOver	4	0n
CompMask	37	0n




SOLD. LAYER


Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypad	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				



Comp.Print	26 On	Comp.Layer	1 On	Comp.Mask	23 On
Solder.Print	29 On	Solder.Layer	4 On	Solder.Mask	28 On
Carbon.Keypos	19 Off	Insulation	20 Off	Carbon.Plate	21 Off
Drill.Drawing	24 On				



PrilDrawing	24	n
CarbonKeypad	18	011
SolderPrint	29	n
CompPrint	28	0n
CompLayer	1	0n
CompMask	27	0n
CarbonPlate	15	011
SolderMask	28	0n



SOLD. MASK

