

## Intertek Testing Services NA, Inc.

Company:	Wave Access	Model:	BR132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:	Feb26,954,953,957,955		


### Worst-Case Line-Conducted Emissions Configuration



## Intertek Testing Services NA, Inc.

Company:	Wave Access	Model:	BR132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:	Feb26,954,953,957,955		

### Worst-Case Line-Conducted Emissions Configuration






## Intertek Testing Services NA, Inc.

Company:	Wave Access	Model:	BR132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:	Feb26,954,953,957,955		


### Worst-Case Radiated Emissions Configuration



## Intertek Testing Services NA, Inc.

Company:	Wave Access	Model:	BR132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:	Feb26,954,953,957,955		

### Worst-Case Radiated Emissions Configuration






## Intertek Testing Services NA, Inc.

Company:	Wave Access	Model:	CU 132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:			


### Worst-Case Radiated Emissions Configuration



## **Intertek Testing Services NA, Inc.**

Company:	Wave Access	Model:	CU 132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:			

### **Worst-Case Radiated Emissions Configuration**





## **Intertek Testing Services NA, Inc.**

Company:	Wave Access	Model:	CU 132
Date:	February 23, 1998	Engineer:	Kouma Sinn
Notes:			

### **Worst-Case Radiated Emissions Configuration**

