

1) According to the data submitted in the test report, there is an emission exceeding the FCC limit at 2737.11 MHz by 1.33 dB. See page 52 of the report).

Response: The wrong set of data was put into the test report. The test report has been revised to show the correct data.

2) Please provide fundamental emissions data for the Z-Axis on all three channels.

Response: The wrong set of data was put into the test report. The test report has been revised to show the correct data.

3) Please provide band-edge measurements for the lower and upper band-edges.

Response: An additional data sheet was added to the test report to show that there were no emissions at the band edges.

4) The FCC statement on the device is incomplete. It is missing the last line of the second item: "including interference that may cause undesired operation." See section 15.19(a)(3) of the rules.

Response: A Revised FCC ID Label has been uploaded.

5) Please provide a signed TCB contract.

This has been uploaded.