


TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2


Internal Photos: Smart ECU 1/2



Front

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2


Internal Photos: Smart ECU 2/2



Rear

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2


Internal Photos: Outside antenna



Front




Rear




Top



Bottom



Top



Bottom

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2

Internal Photos: Inside antenna



Front



Rear



Top




Bottom


Note :Inside antenna does not have any PCB.

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2


Internal Photos: Rear antenna




Front



Rear



Top




Bottom


Note :Rear antenna does not have any PCB.

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2


Internal Photos: Immobilizer antenna 1/2




Front



Rear




Top




Bottom

TOYOTA MOTOR CORPORATION
Smart LF oscillator
FCC ID: NI4TMLF19D-2
IC Number: 2842A-TMLF19D2

Internal Photos: Immobilizer antenna 2/2



Left



Right

Note :Immobilizer antenna has the PCB, but it is not used for an antenna circuit.