

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2


Worst Case Position

ECU
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis




Z-axis




Outside Antenna
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



Worst Case Position

Inside Antenna

Below 30 MHz

X-axis


Above 30 MHz

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



Rear Antenna

Below 30 MHz

X-axis


Above 30 MHz

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



Worst Case Position

Immobilizer Antenna

Below 30 MHz

X-axis

Above 30 MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



Worst Case Position



With transponder key attached



Without transponder key attached (Worst)

End of Report