

Helen Zhao

Subject: FW: Re : FW: Wintecronics Co., Ltd. , FCC ID: NJQWBT100, Assessment NO.: AN05T5376, Notice#1--Updated (1222)

From: daphne.liang [mailto:daphne.liang@tw.ccsemc.com]

Sent: Thursday, December 22, 2005 12:00 AM

To: lucy.tsai; Helen Zhao

Subject: Re : FW: Wintecronics Co., Ltd. , FCC ID: NJQWBT100, Assessment NO.: AN05T5376, Notice#1--Updated(1222)

Dear Helen:

Please find the attached for updated files(1222) and see the belowing reply.
And if still have any problems, please connect with me, thank you very much!

BEST REGARDS

Daphne Liang / ? ? ? 12/22/2005

-----Original Message-----

From: Compliance Certification Services [mailto:helen.zhao@ccsemc.com]

Sent: Monday, December 19, 2005 5:28 PM

Subject: Wintecronics Co., Ltd. , FCC ID: NJQWBT100, Assessment NO.: AN05T5376, Notice#1

Question #1: Please revise FCC ID label format. It shows FCC logo ahead of ID, not using "FCC ID", which is not acceptable. You may put FCC logo separately on the label, but can not replace "FCC" with FCC logo.

Ans:Please find the updated file for ID label format(1222).

Question #2: The schematics show Bluetooth chip BC213159A, but the operational description shows BC215159A. Please explain.

Ans:Please find the updated file for Circuit diagram(1222).

Question #3: The user manual specified 20cm separation distance between end user and the device should be maintained, which is not applicable in this case. Please remove this statement.

Ans:Please find the updated file for User manual(1222).

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

12/22/2005

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.